

USB Virtual Serial Port Driver Installation Instructions In 3 Steps


Step 1:

Click "Start"

Select "Control Panel"




Double-click "Add Hardware"



Click Next >



Click "Yes, I have already connected the hardware"




Click Next>

Scroll all the way down


Select "Add a new hardware device"

Click Next >




Click "Install the hardware that I manually select from a list (Advanced)"

Click Next >




Click Ports (COM & LPT)

Click Next >




Click "(Standard port types)"
Click "Communications Port"

Click "Have Disk..."




Click "Browse . . ."





Locate the file VSP Drivers on the LeadLINK Plus! Software CD
Click "ccservp.inf"

Click Open




Click OK






Click Next>




Click Next>


Click "Continue Anyway"



Click "Continue Anyway"




Click Finish



Step 2:


Determining the Com Port to use with your PC

Double-Click "System"




Click "Hardware"


Click "Device Manager"




Double-click on
Ports (COM & LPT)
Find "USB to Virtual
Com Port (COM4)"



Click File
Click Exit




Click OK



Click File

Click Close



CompuSystems, Inc.
2805 S. 25th Avenue
Broadview, IL 60155
708.786.5565

Step 3:


First-->

- >>Power on the CompuLEAD II Unit with the switch on the back of unit
- >>Wait for LCD display to light up
- >>Connect the USB Cable in the back of CompuLEAD II Unit
- >>Connect the USB Cable on your PC

Then . . .



You will see this message at the lower right hand corner of the desktop




Click "No, not this time"


Click Next >

Click "Install from a list or specific location (Advanced)"

Click Next >




Click "Include this location in the search:"
Click "Browse"





Locate the "USB Virtual ComPort Driver"

Click OK




Click Next >






Click "Continue Anyway"



Click Finish

Once CL2 is installed
you will see this message



You Are Done!

If you need assistance installing your USB Virtual Serial Port Driver
please contact a technical support specialist at 708-786-5565.